



JBH:tja/cmw 6/25/07 6454-66361-01 609637 QP97011-A US

*off c.*  
PATENT  
Attorney Matter No. 6454-66361-01

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

**In re application of:** Keefer et al.

**Date Mailed** June 29, 2007

**Patent No.** 7,094,275

**Issued:** August 22, 2006

**Application No.** 10/620,262

**Filed:** July 14, 2003

**Confirmation No.** 8753

**For:** MODULAR PRESSURE SWING  
ADSORPTION APPARATUS

**Certificate**

**Examiner:**

**JUL 10 2007**

**Art Unit:** 3744

**Attorney Reference No.** 6454-66361-01

**of Correction**

COMMISSIONER FOR PATENTS  
P.O. BOX 1450  
ALEXANDRIA, VA 22313-1450

**REQUEST FOR CERTIFICATE OF CORRECTION**

The following printing errors were noted in comparing the printed patent with the papers in the attorneys' files:

**In the Specification:**

Column 1, Line 26, "cl BACKGROUND OF THE INVENTION" should be a section

heading and should read -- BACKGROUND OF THE INVENTION --

Column 2, Line 44, "cl SUMMARY OF THE INVENTION" should be a section heading  
and should read -- SUMMARY OF THE INVENTION --

Column 8, Line 63, "are" should read -- arc --

Column 9, Line 20, "along" should read -- long --

Column 20, Line 23, "3711B" should read -- 371B --

Column 24, Line 14, "face..." should read -- face. --

*JUL 10 2007*

PATENT  
Attorney Matter No. 6454-66361-01

All of the above errors are attributable to the Patent Office, and a Certificate of Correction is enclosed in duplicate to make formal notice of the errors in the referenced patent.

Respectfully submitted,

KLARQUIST SPARKMAN, LLP

One World Trade Center, Suite 1600  
121 S.W. Salmon Street  
Portland, Oregon 97204  
Telephone: (503) 595-5300  
Facsimile: (503) 595-5301

By



\_\_\_\_\_  
Jeffrey B. Haendler  
Registration No. 43,652

cc: Docketing

JUL 10 2007

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO. : 7,094,275

DATED : August 22, 2006

INVENTOR(S) : Keefer et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the Specification:

Column 1, Line 26, "cl BACKGROUND OF THE INVENTION" should be a section heading and should read -- BACKGROUND OF THE INVENTION --

Column 2, Line 44, "cl SUMMARY OF THE INVENTION" should be a section heading and should read -- SUMMARY OF THE INVENTION --

Column 8, Line 63, "are" should read -- arc --

Column 9, Line 20, "along" should read -- long --

Column 20, Line 23, "3711B" should read -- 371B --

Column 24, Line 14, "face..." should read -- face. --

MAILING ADDRESS OF SENDER:  
Klarquist Sparkman, LLP  
One World Trade Center, Suite 1600  
121 SW Salmon Street  
Portland, Oregon 97204

PATENT NO. 7,094,275  
No. of add'l copies 0  
(@ .30 per page)

JUL 10 2007  
Page 1 of 1

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO. : 7,094,275

DATED : August 22, 2006

INVENTOR(S) : Keefer et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the Specification:

Column 1, Line 26, "cl BACKGROUND OF THE INVENTION" should be a section heading and should read -- BACKGROUND OF THE INVENTION --

Column 2, Line 44, "cl SUMMARY OF THE INVENTION" should be a section heading and should read -- SUMMARY OF THE INVENTION --

Column 8, Line 63, "are" should read -- arc --

Column 9, Line 20, "along" should read -- long --

Column 20, Line 23, "3711B" should read -- 371B --

Column 24, Line 14, "face..." should read -- face. --

MAILING ADDRESS OF SENDER:

Klarquist Sparkman, LLP  
One World Trade Center, Suite 1600  
121 SW Salmon Street  
Portland, Oregon 97204

PATENT NO. 7,094,275

No. of add'l copies 0  
(@ .30 per page)

Page 1 of 1

JUL 10 2007